A Company of ThyssenKrupp Technologies

G&L Motion Control, LLC



Memo

To All Registered Users of PiCPro

From Sue Dorscheid

CC:

Date 16-Dec-04

Regarding PiCPro Automatic Updates

On December 13, the location of the PiCPro Service Pack website was moved to a new server. This causes PiCPro's automatic update feature to fail with an Internet connection error. PiCPro's automatic update can be initiated 4 different ways:

- 1. After installation of a base version of PiCPro (either CD or download), there is an option to check for updates.
- 2. From the Start Menu, there is an icon that will check for updates.
- 3. From within PiCPro under the help menu, there is a menu item to check for updates.
- 4. At a timed interval, PiCPro can automatically check for updates (silent mode).

This affects all editions of PiCPro - V13, V14 and V14.1 - with or without an applied service pack.

If you use the automatic update feature, a patch has been released to fix this problem and can be found on our website:

http://www.glcontrols.com/ie/technicalinformation/install_errors.asp

The patch will be installed on a computer and a menu item created at "Start | All Programs | Service Pack Auto Update Patcher". This patch should be run anytime PiCPro is re-installed or a service pack is applied.

If you don't use the auto-update feature, you do not need to apply this patch. You can still download service packs directly from the website as in the past.